GOVERNMENT OF KARNATAKA
Public Works Department

No. AEE: No.2/NSD:2026-27/557

Office of the Assistant Executive Engineer
PWD, NO.2 North Sub-Division, Bangalore
Dated: 25-09-2026

BUILDING SAFETY CERTIFICATE

It is Certified that the existing building **Shiksha Central School** at No. 4/4, Gangondanahalli, Lakshmipur Post, Dasanapura Hobli, Bengaluru 562162 is having block(s)/Floors(s) as per details below.

Details of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)
No. of Floors (s) in the Block	**G+2**	-	-	-	-

The building is owned/ occupied by **Shiksha Central School** have complied with the building safety Requirements as NDT test carried out by Keystone Engineering Solution-QC Lab, No.6, 3rd Main, Ganganagar, Mariyappanapalya, Bangalore 560056 (NABL accredited Testing Lab) on 24.09.2026 in the presence of the Administrative Officer, **Shiksha Central School** and that the building/premises of **Shiksha Central School** are deemed fit for occupancy to operate the school, effective from 25.09.2026 and valid till 24.09.2029, in accordance with rule and subject to compliance of the specific conditions as appended.

1. Prevent movement of students at Terrace and safety measures to be taken
2. General periodical maintenance for overall building.
3. Any modifications, Additions and Alterations must be carried out under strict technical guidance and supervision.

Issued on 25.09.2026 at Bangalore by Assistant Executive Engineer, PWD Office.

Assistant Executive Engineer
P.W.D. No. 2, North Sub-Division
K.R. Circle, Bengaluru

SECRETARY
GRS EDUCATION TRUST
No. 232, 8th Cross, HMT Layout,
Bangalore - 560 073.

PRINCIPAL
SHIKSHA CENTRAL SCHOOL
No. 4/4, Gangondanahalli,
Bangalore - 562 162